

# LOW PRESSURE DIE CASTING

*We are serving of*



1. Melting Furnace
2. Heat Recycle System
3. Regenerative Burner
4. Immersion Heater
5. Degassing System
6. Ladle Preheating
7. Holding Furnace with Immersion Heater and Double Chamber
8. Casting Machine (LPM / IDRA)
9. CNC Machine
10. Heat Treatment
11. Furnace Control System
12. Helium Leak Testing Machine
13. X-ray
14. Waste Recycle for Chips
15. Waste Recycle for dross